

SOFTWARE

INCREASED STAND BY TIME

6.10.2007

I could not find so much information out there about the HP Ipaq hw6515 power surge – my device runs on battery only a few hours if both GSM and GPS are being enabled. After several unsuccessful attempts I found only two options to prolonge battery life – disabling both SD card slots and by CPU clocking down from ~300 to ~100 Mhz.

CC-BY-NC Science Surf accessed 13.12.2025 
